

www.exacq.com

DATE OF PUBLICATION: **09/26/2016**

CHANGE NOTIFICATION #: 1001

PLANNED DATE OF CHANGE:

Bentel manufactured systems: 10/1/2016 Fishers manufactured systems: 10/15/2016

SUMMARY OF CHANGE:

Discontinuance of internal DVD burner on exacqVision Z-Series recorders and S-Series storage servers.

DESCRIPTION AND REASON FOR CHANGE:

Due to the increasing capacity and performance of USB flash drive storage as an export media, demand for exporting to writeable DVD discs has diminished. To reflect changing demands Exacq is discontinuing the internal DVD burner on exacqVision Z-Series recorders as well as S-Series storage servers.

Systems built without a DVD burner will have a color-matched blank insert on the face of the chassis where the DVD burner previously existed.

For customers that need DVD burning functionality, an external DVD burner is available to use with all A-Series, Z-Series and S-Series hardware.

Part Number	Description
5000-50500	exacqVision External USB DVD-RW Drive

PART NUMBERS AFFECTED BY THIS CHANGE:

Part Number	Description
xx08-xxT-R2Z	2U, hybrid Z-Series recorders
xx08-xxT-R4Z	4U, hybrid Z-Series recorders
IP08-xxT-R2Z	2U, IP Z-Series recorders
IP08-xxT-R4Z	4U, IP Z-Series recorders
S-xxT-2U	2U, S-Series storage server
S-xxT-4U	4U, S-Series storage server