

DATE OF PUBLICATION: 10/6/2016

CHANGE NOTIFICATION #: 1002

PLANNED DATE OF CHANGE:

Bentel manufactured systems: 12/1/2016

Fishers manufactured systems: 12/1/2016

SUMMARY OF CHANGE:

Discontinuance of internal DVD burner on exacqVision A-Series 2U recorders.

DESCRIPTION AND REASON FOR CHANGE:

Due to the increasing capacity and performance of USB flash drive storage as an export media, demand for exporting to writeable DVD discs has diminished. To reflect changing demands, Exacq is discontinuing the internal DVD burner on exacqVision A-Series 2U recorders.

Systems built without a DVD burner will have a color-matched blank insert on the face of the chassis where the DVD burner previously existed.

For customers that need DVD burning functionality, an external USB DVD burner is available to use with all A-Series, Z-Series and S-Series hardware.

Part Number	Description
5000-50500	exacqVision External USB DVD-RW Drive

PART NUMBERS AFFECTED BY THIS CHANGE:

Part Number	Description
IP04-xxT-R2A	2U, A-Series IP recorders
xx08-xxT-R2A	16 & 32-input A-Series hybrid recorders
